Name(s) of Risk Team Members: R. Savage and J. Scott			Point Value → Parameter ↓	1					2	3	4				5		
Area/Facility Description Title: Collider-Accelerator Department Area/Facility # (if applicable): Facility-Wide FRA 5-05			Occupancy or Use (A)	≤once/year			ar		≤once/month	≤once/week	≤once/shift		>once/shift				
Area/Facility Description: Facility-Wide Housekeeping Approved by: £. Lessard Date: 3/21/05 Rev.#: 0			Severity (B)	Fi	First Aid Only Extremely Unlikely				Medical Treatment	Lost Time	Partial Disability Probable		ity	Death or Permanent Disability			
			Likelihood (C)	Extr				7	Unlikely	Possible			ole		Multiple		
Reason for Revision (if applicable):		1							Comments:							
					Before Additional Controls				<u> </u>			After Additional Controls					
Physical Item or Activity	Hazard(s)	Control(s)			Occupancy A	Severity B	Likelihood C	Risk* AxBxC	Cont	Control(s) Added to Reduce Risk			Severity B	Likelihood C	Risk* AxBxC	% Risk Reduction	
Walking – working surfaces Falls on same level Tier 1; work planning; skill of craft; P.I. internal and external audits; posting; lal communication; internal processes; less identified outside walking/working surrepair. PE instituted a program to correshovels and salt were distributed to staff walkways in winter storms. A safety cl Working Surfaces was distributed to staff updated to indicate that work performed slipping and falling shall be classified a hazard job and will require additional rework Permit.			beling; training; barriers; sons learned. C-A staff faces that are in need of ect deficiencies. Snow ff for emergency use on checklist: Walking and laff. C-A O.P.M. 2.28.d was dwith risk factors of at a minimum as a modera	/as	as				C-AD Housekeeping Policy and OPM 1.7, Supervisory Practice for Working with Hazards were enhanced to reinforce C-AD commitment to housekeeping practices. Supervisors were reminded to have their respective personnel read the OPM. In addition, C-AD Senior Management involvement in Tier I Inspections has focused on Building Manager responsibilities concerning housekeeping issues.				3	3	45	25 %	
Storage	Being struck by an object, such as a tool falling on a worker from above	Tier 1; inventory control; work planning internal and external audits; training; control; procedures; lessons learned, no storage electrical panels or disconnects.	ommunication; internal		4	5	2	40									
Egress	ress Impaired egress Tier 1; work planning; skill of craft; I internal and external audits; posting; communication; internal processes; le codes; emergency preparedness		beling; training; barriers;		4	4	2	32									
inter HVA		Fier 1; work planning; skill of craft; P.E. scheduled maintenance; internal and external audits; posting; labeling; training; barriers; HVAC maintenance, ventilation, IH monitoring as required.			4	3	3	36									
Further Description of C	Controls Added to Reduce Ris	k:															
*Risk:	0 to 20	21 to 40			41-60				6	to 80		81 or	greate	r			
Negligible		Acceptable			Moderate				S	Substantial			Intolerable				